

REPAIR SERVICE BOX PROGRAM

Mercury Medical will provide a Special Repair Service Box to your facility at no charge to assist with your medical equipment repair needs.

Repairs are logged by requesting a Return Authorization Form (RAF) from the Clinical Services Division at **1-800-990-MERC** or email us at: techserviceadministration@mercurymed.com.



Blenders:*

Standard Hi/Lo Flow Blender (Only) Overhaul*	\$405.00/ea
<i>with flowmeters, add per flowmeter replaced.</i>	\$45.00/ea (specialty flowmeters extra)
Large Block Blender (Only) Overhaul*	\$675.00/ea
<i>with flowmeters, add per flowmeter replaced.</i>	\$45.00/ea (specialty flowmeters extra)

3 or More Units

Suction Regulators:*

Continuous/Intermittent Suction Regulator - Standard Repair/Calibration*	\$90.00/ea
<i>Adapter replacement (cost will be determined at time of evaluation).</i>	
*Does Not include Boehringer Regulators	
<i>(S/N Series below 20000 are no longer repairable per manufacturer).</i>	

3 or More Units

Respirometers:*

Standard Respirometer Calibration Service, i.e., Ferraris, Mark 14	\$205.00/ea
Standard Respirometer Repair/Calibration Service, i.e., Ferraris, Mark 14*	
Large Dial Respirometer Repair/Calibration Service, i.e., FDE*	
<i>(cost will be determined at time of evaluation).</i>	

3 or More Units



* An Overhaul includes internal overhaul parts as required by the manufacturer.
Blenders do not include knobs, face plates, adapters or stop pins.
Suction Regulators do not include housings, dials or adapters.
Respirometers do not include lenses, respirometer dial, hands, main plates or broken/missing accessories.
 Additional items requiring replacement will be quoted at the time of evaluation.